



REPORT OF INSPECTION IN ACCORDANCE WITH THE MEMORANDUM OF UNDERSTANDING ON PORT STATE CONTROL IN THE ASIA-PACIFIC REGION 1)

(reporting authority) : Marine Department of Thailand  
(address) : 1278 Yotha Road, Sampantawong, Bangkok, Thailand  
(telephone) : (662)2331311-8  
(talafax) : (662)2366678  
(e-mail address) : psc@md.go.th

copy to: master  
head office  
PSCO  
if ship is detained, copy to:  
flag State  
IMO  
Recognized organization, if applicable

1 name of reporting authority MALAYSIA Marine Department of Thailand 2 name of ship MT STRAITS ENERGY  
3 flag of ship 9411149 4 type of ship OIL TANKER 5 call sign 9MRR97 533131065  
6 IMO number 1410412007 7 gross tonnage 4570 8 deadweight (where applicable) 6190  
9 year of build 14.04.2007 10 date of inspection 22.09.2024 11 place of inspection RAYONG  
12 classification society CCS 13 date of release from detention<sup>2)</sup>  
14a IMO company number 5653232 14b particulars of company MAY TANKER SDN BHD.

15 name and signature of master to certify that the information under 14 is correct:  
name A. FAHRUWAN AMIN signature



a title	b issuing authority	c date of issue and expiry
1 Load Line Cert.	CCS	02.11.2023 - 02.08.2028
2 Cargo Ship Safety Construction Cert.	CCS	02.11.2023 - 02.08.2028
3 Cargo Ship Safety Equipment Cert.	CCS	02.11.2023 - 02.08.2028
4 Cargo Ship Safety Radio Cert.	CCS	02.11.2023 - 02.08.2028
5 IOPP Cert.	CCS	02.11.2023 - 02.08.2028
6 Minimum Safe Manning Document.	FS	12.08.2020 - 10.08.2025
7 International Tonnage Cert.	KR	01.11.2019
8 D O C	FS	29.07.2020 - 30.07.2025
9 S M C	CCS	05.10.2020 - 04.10.2025
10 ISSC	CCS	30.09.2020 - 29.09.2025
11 MLC	CCS	01.10.2020 - 30.09.2025
12		

d information on last intermediate or annual survey

date	surveying authority	place
1		
2		
3		
4		
5		
6		
7		
8	FS	PORT KELANG
9	CCS	BATAM
10	CCS	BATAM
11	CCS	BATAM
12		



MARINE OFFICE 6, RAYONG BRANCH SHIP SURVEYOR

17 deficiencies  no  yes (see attached Form B)  
18 ship detained  no  yes<sup>3)</sup>  
19 supporting documentation  no  yes (see annex)

issuing office Marine Department, Thailand name MR. SEKSUN P., MR. SAROCH T., MR. TOSSARON M.  
(duly authorized PSCO of reporting authority)  
telephone +6622331311-8 signature [Signatures]  
talafax +6622366678

This report must be retained on board for period of two years and must be available for consultation by Port State Control Officers at all times.

1) This inspection report has been issued solely for the purpose of informing the master and other port State that an inspection by the port State, mentioned in the heading, has taken place. This inspection report cannot be construed as a seaworthiness certificate in excess of the certificates the ship is required to carry.  
2) To be completed in the event of a detention.  
3) Masters and companies are advised that detailed information on a detention may be subject to future publication.





REPORT OF INSPECTION IN ACCORDANCE WITH THE MEMORANDUM OF UNDERSTANDING ON PORT STATE CONTROL IN THE ASIA-PACIFIC REGION

(reporting authority) : Marine Department of Thailand
(address) : 1278 Yotha Road, Sampantawong, Bangkok, Thailand
(tel/fax) : (662)2331311-8
(tel/fax) : (662)2366678
(e-mail address) : psc@md.go.th

copy to: master
head office
PSCO
if ship is detained, copy to:
flag State
IMO
Recognized organization, if applicable

2 name of ship STRAITS ENERGY
10 date of inspection 22.02.2024
6 IMO number 9477749
11 place of inspection RAYONG


20 number 21 code nature of deficiency
convention Reference 22 action taken 23 responsible RO 24 ISM Related

1 04103 3 EMERGENCY LIGHTING IN MEETING ROOM WERE UNLIT

17/10

2 09103 ACCOMMODATION A/C CIRCULATE LINE FRAME SCREEN FILTER WAS DIRTY

17/10



Signature of Master: Capt Fajonwan Amin

Signature of PSCO: M.P. SENSUD I, M.P. GAROCH J, M.R. TOSSAPON M
MARINE OFFICE 6, RAYONG BRANCH SHIP SURVEYOR

4) This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of detention, it is recommended that full survey is carried out and all deficiencies are rectified before an application for re-inspection is made.
5) To be completed in the event of a detention.
6) Applicable Deficiency Action Codes (see reverse side of copy) to be entered.